MISSISSIPPI STATE DEPARTMENT OF HEALTH 2016 SEP 30 AM 8: 23
BUREAU OF PUBLIC WATER SUPPLY
CCR CERTIFICATION
CALENDAR YEAR 2015
Public Water Supply Name 056006 0560014

List PWS ID #s for all Community Water Systems included in this CCR

The Federal Safe Drinking Water Act (SDWA) requires each Community public water system to develop and distribute a Consumer Confidence Report (CCR) to its customers each year. Depending on the population served by the public water system, this CCR must be mailed or delivered to the customers, published in a newspaper of local circulation, or provided to the customers upon request. Make sure you follow the proper procedures when distributing the CCR. You must mail, fax or

| la copy of the CCR and Certification to MSDH. Please check all boxes that apply.  |
|---|
| Customers were informed of availability of CCR by: (Attach copy of publication, water bill or other)  |
| Advertisement in local paper (attach copy of advertisement)  On water bills (attach copy of bill)  Email message (MUST Email the message to the address below)  Other   |
| Date(s) customers were informed:/,/   |
| CCR was distributed by U.S. <u>Postal Service</u> or other direct delivery. Must specify other direct delivery methods used   |
| Date Mailed/Distributed:/_/   |
| CCR was distributed by Email (MUST Email MSDH a copy)  O As a URL (Provide URL  O As an attachment  O As text within the body of the email message  |
| CCR was published in local newspaper. (Attach copy of published CCR or proof of publication)  |
| Name of Newspaper: Richton DispateH   |
| Date Published: June / 9 /2016  |
| CCR was posted in public places. (Attach list of locations)  Date Posted: 66/14/2016  |
| CCR was posted on a publicly accessible internet site at the following address ( <b>DIRECT URL REQUIRED</b> ):  |
| EIFICATION  eby certify that the 2015 Consumer Confidence Report (CCR) has been distributed to the customers of this ic water system in the form and manner identified above and that I used distribution methods allowed by DWA. I further certify that the information included in this CCR is true and correct and is consistent with water quality monitoring data provided to the public water system officials by the Mississippi State artment of Health, Bureau of Public Water Supply. |
|   |

HLLEN Loff PRESICE
Name/Title (President, Mayor, Owner, etc.

Sept-27-2016

Deliver or send via U.S. Postal Service: Bureau of Public Water Supply P.O. Box 1700 Jackson, MS 39215

May be emailed to:

May be faxed to:

(601)576-7800

CCR Due to MSDH & Customers by July 1, 2016!

water.reports@msdh.ms.gov

# 2015 Annual Drinking Water Quality Report Arlington Water Association PWS#: 0566996 & 0560014 AM 8: 48

2016 AUG II AM 8:

'ED-WATER SUI

We're pleased to present to you this year's Annual Quality Water Report. This report is designed to inform you about the quality water and services we viene pleased to present to you this years Annual Quality water Report. This report is designed to inform you about the quality water and services we deliver to you every day. Our constant goal is to provide you with a safe and dependable supply of drinking water. We want you to understand the efforts we make to continually improve the water treatment process and protect our water resources. We are committed to ensuring the quality of your water. Our water source is from wells drawing from the Hattlesburg Formation and Miocene Series Aquifer.

The source water assessment has been completed for our public water system to determine the overall susceptibility of its drinking water supply to identified potential sources of contamination. A report containing detailed information on how the susceptibility determinations were made has been furnished to our public water system and is available for viewing upon request. The wells for the Arlington Water Association have received lower susceptibility rankings to contamination.

If you have any questions about this report or concerning your water utility, please contact Allen Lott at 601-588-0493. We want our valued customers to be informed about their water utility. If you want to learn more, please attend any of our regularly scheduled meetings. They are held on the last Tuesday of each month at 7:00 P.M. at the water office.

We routinely monitor for constituents in your drinking water according to Federal and State laws. This table below lists all of the drinking water contaminants that were detected during the period of January 1st to December 31st, 2015, in cases where monitoring wasn't required in 2014, the table reflects the most recent results. As water travels over the surface of land or underground, it dissolves naturally occurring minerals and, in some cases, radioactive materials and can pick up substances or contaminants from the presence of animals or from human activity; microbial contaminants, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife; inorganic contaminants, such as salts and metals, which can be naturally occurring or result from urban storm-water runoff, industrial, or domestic wastewater discharges, oil and gas production, mining, or farming; posticides and herbicides, which may come from a variety of sources such as agriculture, urban storm-water runoff, and residential uses; organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations and septic systems; radioactive contaminants, which can be naturally occurring or be the result of oil and gas production and mining activities. In order to ensure that tap water is safe to drink, EPA prescribes regulations that limit the amount of certain contaminants in water provided by public water systems. All drinking water, including bottled drinking water, may be reasonably expected to contain at least small amounts of some constituents. It's important to remember that the presence of these constituents does not necessarily indicate that the water poses a health risk.

In this table you will find many terms and abbreviations you might not be familiar with. To help you better understand these terms we've provided the following definitions:

Action Level - the concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Maximum Contaminant Level (MCL) - The "Maximum Allowed" (MCL) is the highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.

Maximum Contaminant Level Goal (MCLG) - The "Goal" (MCLG) is the level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Maximum Residual Disinfectant Level (MRDL) - The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG) - The level of a drinking water disinfectant below which there is no known or expected risk of health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

Parts per million (ppm) or Milligrams per liter (mg/l) - one part per million corresponds to one minute in two years or a single penny in \$10,000.

Perts per billion (ppb) or Micrograms per liter - one part per billion corresponds to one minute in 2,000 years, or a single penny in \$10,000,000.

| PWS ID#:0560006 |                  | TEST RESULTS      |                   |   |                          |      |          |  |
|-----------------|------------------|-------------------|-------------------|---|--------------------------|------|----------|--|
| Contaminant     | Violation<br>Y/N | Date<br>Collected | Level<br>Detected | Range of Detects<br>or # of Samples<br>Exceeding<br>MCL/ACL | Unit<br>Measure<br>-ment | MCLG | MCL      | Likely Source of Contamination   |
| Inorganic       | Contar           | ninants           |                   |   |                          |      |          |  |
| 10. Barium      | N                | 2013*             | .1134             | No Range  | ppm                      | 2    | 2        | Discharge of drilling wastes; discharge from<br>metal refineries; erosion of natural deposits                |
| 13. Chromium    | N                | 2013*             | 1.2               | No Range  | ppb                      | 100  | 100      | Discharge from steel and pulp mills;<br>erosion of natural deposits  |
| 14. Copper      | N                | 2012/14           | .2                | 0   | ppm                      | 1.3  | AL=1.3   | Corrosion of household plumbing systems;<br>erosion of natural deposits; leaching from<br>wood preservatives |
| 17. Lead        | N                | 2012/14           | 1                 | 0   | ppb                      | 0    | AL=15    | Corrosion of household plumbing systems, erosion of natural deposits   |
| Disinfection    | on By-P          | roducts           | <u> </u>          |   |                          |      |          |  |
| Chlorine        | ΤŃ               | 2015              | 0.85              | 1-1.5   | mg/l                     | 0 MF | DL = 4 V | Vater additive used to control microbes  |

### SIGNIFICANT DEFICIENCY SUMMARY REPORT

• During a sanitary survey conducted on 8/19/2014, the Mississippi State Department of Health cited the following significant deficiency: G201 - Lack of redundant mechanical components where treatment is required. Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiration of the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

During a sanitary survey conducted on 8/19/2014, the Mississippi State Department of Health cited the following significant deficiency: G701 - No approved emertonics.

gency response plan or vulnerability analysis (updated annually). Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiration of the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

• During a sanitary survey conducted on 8/19/2014, the Mississippi State Department of Health cited the following significant deficiency: G200 - Inadequate application of treatment chemicals and techniques (primary MCLs). Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiration of the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

• During a sanitary survey conducted on 10/21/2013, the Mississippi State Department of Health cited the following significant deficiency: G502 - Inadequate/inoperable control system. Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiration of the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

| PWS ID#:                              | 056001           | 14                | <b>T</b> ]        | EST RESUL   | TS                                  |                                       |   |  | •                                      |
|---------------------------------------|------------------|-------------------|-------------------|---|-------------------------------------|---------------------------------------|---|--|--|
| Contaminant                           | Violation<br>Y/N | Date<br>Collected | Level<br>Detected | Range of Detects<br>or # of Samples<br>Exceeding<br>MCL/ACL | Unit<br>Measure<br>-ment            | MCLG                                  | MCL   |  | Likely Source of<br>Contamination      |
| Microbiol                             |                  |                   |                   |   | nenewest matrix or agree of the ac- | ************************************* | MARKA SINI SINI NI |  |  |
| 1. Total Coliform Y Janua<br>Bacteria |                  | January           | Positive          | 4   | NA NA                               |                                       | 0 p   | bresence of coliform<br>bacteria in 5% of<br>monthly samples   | Naturally present<br>in the environmen |
| Inorganic                             | Contar           | ninants           |                   |   |                                     |                                       |   |  |  |
| 10. Barium                            | N                | 2013*             | .0022             | No Range  | ppm                                 | 2                                     | 2   | Discharge of drilling wastes; discharge from metal refineries; erosion of natura deposits                    |  |
| 14. Copper                            | N                | 2012/14           | .3                | 0   | ppm                                 | 1.3                                   | AL=1.3  | Corrosion of household plumbing<br>systems; erosion of natural deposits;<br>leaching from wood preservatives |  |
| 17. Lead                              | Ň                | 2012/14           | :2                | 0   | ppb                                 | . 0                                   | AL=15   | Corrosion of household plumbing systems, erosion of natural deposits   |  |
| Disinfection                          | n By-P           | roducts           | 3                 |   |                                     |                                       | *   | ,  | *                                      |
| Chlorine                              | N                | 2015              | 1.2               | 1.1 - 1.90  | mg/l                                | 0                                     | MRDL = 4  | 4 Water additive used to control microbes  |  |

<sup>\*</sup> Most recent sample. No sample required for 2014.

Microbiological Contaminants:

(1) Total Coliform. Coliforms are bacteria that are naturally present in the environment and are used as an indicator that other, potentially-harmful, bacteria may be present. Coliforms were found in more samples than allowed and this was a warning of potential problems.

Both our systems received a CCR Adequacy/Availability/Content violation for the Consumer Confidence Rule.

We routinely monitor for the presence of drinking water contaminants. In January of 2014, 4 samples showed the presence of coliform bacteria. The standard is that no more than 1 sample per month of our samples may do so. The resamples also showed the presence of bacteria. After a boil water notice, we did not find any bacteria in our subsequent testing and further testing shows that this problem has been solved. We also have a violation for not giving public notice.

We are required to monitor your drinking water for specific constituents on a monthly basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. In an effort to ensure systems complete all monitoring requirements, MSDH now notifies systems of any missing samples prior to the end of the compliance period.

#### VIOLATIONS

23 - Monitoring (TCR), Routine Major Violation Period: 10/01/15 - 10/31/15 Coliform (TCR) Not Complete 27 - Monitoring, Routine (DBP), Major Violation Period: 10/01/15 - 12/31/15 Chlorine Not Complete

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. Our water system is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or at http://www.epa.gov/safewater/lead. The Mississippi State Department of Health Public Health Laboratory offers lead testing. Please contact 601.576.7582 if you wish to have your water tested.

All sources of drinking water are subject to potential contamination by substances that are naturally occurring or man made. These substances can be microbes, inorganic or organic chemicals and radioactive substances. All drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the Environmental Protection Agency's Safe Drinking Water "Hotline at 1-800-426-4791.

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by cryptosporidium and other microbiological contaminants are available from the Safe Drinking Water Hotline 1-800-426-4791.

The Arlington Water Association works around the clock to provide top quality water to every tap. We ask that all our customers help us protect our water sources, which are the heart of our community, our way of life and our children's future.

June 2016

2016 SEP 30 AM 8: 23

CENTED-WATER SUNT

n

36

0 u

ou

SSI

əjí

ιqį

Si

TEST RESULTS WS ID#:0560006 Likely Source of Contamination MCL MCLG Range of Detects Level Violation Date ontaminant Measure or # of Samples Detected Collected Y/N Exceeding MCL/ACL -ment norganic Contaminants Discharge of drilling wastes; discharge from metal refineries; erosion of natural deposits 2 .1134 No Range ppm 2013\* 0. Barium Discharge from steel and pulp mills; 100 100 ppb No Range 2013\* 1.2 N 3. Chromium erosion of natural deposits Corrosion of household plumbing systems; AL=1.3 1.3 0 ppm 2012/14 .2 erosion of natural deposits; leaching from 4. Copper wood preservatives Corresion of household plumbing AL=15 ppb n 2012/14 7. Lead systems, erosion of natural deposits Disinfection By-Products MRDL = 4 | Water additive used to control microbes 0 .0.85

## **IGNIFICANT DEFICIENCY SUMMARY REPORT**

• During a sanitary survey conducted on 8/19/2014, the Mississippi State Department of Health cited the following significant deficiency: G201 - Lack of redundant sechanical components where treatment is required. Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiration f the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

During a sanitary survey conducted on 8/19/2014, the Mississippi State Department of Health cited the following significant deficiency: G701 - No approved emer-beneath ency response plan or vulnerability analysis (updated annually). Corrective Actions: MSDH is currently working with this system to return them to compliance since ne expiration of the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

• During a sanitary survey conducted on 8/19/2014, the Mississippi State Department of Health cited the following significant deficiency: G200 - Inadequate application f treatment chemicals and techiniques (primary MCLs). Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiraon of the compliance deadline. We anticipate the system being returned to compliance by 6/30/2016.

• During a sanitary survey conducted on 10/21/2013, the Mississippi State Department of Health cited the following significant deficiency: G502 - Inadequate/inoperale control system. Corrective Actions: MSDH is currently working with this system to return them to compliance since the expiration of the compliance deadline. We inticipate the system being returned to compliance by 6/30/2016.

| PWS ID#:                      | Violation | Date      | Level    | ST RESUL Range of Detects               | Unit             | MCLG                             |          | MCL  | Likely Source of                    |
|-------------------------------|-----------|-----------|----------|---|------------------|----------------------------------|----------|--|-------------------------------------|
| Sunamilalit                   | Y/N       | Collected | Detected | or # of Samples<br>Exceeding<br>MCL/ACL | Measure<br>-ment |                                  |          |  | Contamination                       |
| Microbiol                     | ogical (  | Contam    | inants   |   |                  |                                  |          |  |                                     |
| 1. Total Coliform<br>Bacteria |           | January   | Positive |   | NA               |                                  | 0 рі     | resence of coliform<br>bacteria in 5% of<br>monthly samples  | Naturally present in the environmen |
| Inorganic                     | Contai    | ninants   | 4 (\$    |   |                  |                                  |          |  |                                     |
| 10. Barium                    | N         | 2013*     | .0022    | No Range                                | ppm              | 2                                |          | Discharge of drilling wastes; dischar<br>from metal refineries; erosion of nati<br>deposits  |                                     |
| 14. Copper                    | N         | 2012/14   | .3       | 0                                       | ppm              | 1.3                              | A.       |  |                                     |
| 17. Lead                      | N         | 2012/14   | 2        | 0                                       | ppb              | 0                                | AI =15   | The second secon |                                     |
| Disinfection                  | on By-I   | Product   | <b>S</b> |   |                  | 1 (1)<br>1 (1)<br>1 (1)<br>1 (1) |          |  |                                     |
| Typinicon,                    | IN .      | 2015      | 1.2      | 1.1 - 1.90                              | mg/l             | 0                                | MRDL = 4 | 4 Water additive used to control microbes  |                                     |

<sup>(1)</sup> Total Coliform. Coliforms are bacteria that are naturally present in the environment and are used as an indicator that other, potentially-harmful, bacteria may be present. Coliforms were found in more samples than allowed and this was a warning of potential problems.